Work Orde June-24-13 1:57		3515		*103	3515*						Page 1
Revision ID:	646.3316 Blade			Accept	*N9000	140	100)* s	etup Star Stop	I VI	S1*
	6/24/13	Start Qty: 10.00 Req'd Qty: 10.00	*1 0 * *1 0 *		Cust Item ID Customer;	: '				14	. 17
Approvals:	Process PI	an: _ HLJ	Date: \\\\	C Tooling: SPC (Y/N):	Date		- 	,R	tun Star Stop	" IV	R1* R2*
Sequence ID/ Work Center II)	Operation Description		Set Up/ Run Hours	Tool ID	Tool#	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Re	vision Nbr		-							
646.3300	N/0	C		;							
*100 *100* Bandsaw Jeaspa Bandsaw	,,	BAND SAW Memo Cut Blank a	1 6.000"	0.00	Shi	3-07-	-28	ĺΰ	æ		
*110 *110* HAAS 1 HAAS CNC vertical	machine #1	HAAS CNC VERTICAI Memo 1-Machine p DWG REV; FOLIO REV	per folio FB147	0.00	S\$ 13-07-7	28		10	Ø		. ———

2- deburr and break all sharp edges except otherwise noted

DQA:		_ Date:											•	` λΔRT
QA Closed:		Date:			WORK ORDER NON-	-C(ONFO	RMANCE / UI		Wo	rk Order up	odate only	\neg	AEROSPACE
					DISPOSITION	-			-		ARTMENT			
Work Orde	er:					1		🗂	,		-	_	_	
Part N	lo.				Rework Scrap			Skid-tube Machining	Crosstube Small Fab		Pro	Water Jet d. Eng. Coor.	\dashv	Engineering Quality
				_	Use-as-is			noforming	Finishing	_		re/Packaging	╗	Other
NCR N	lo			_	Suspected Unapproved			Large Fab	Composite	\vdash		Supplier		
Root				Desci	ription of work order update		Initial	Act	ion		Sign &			
Cause	Date	Step	Qty		or non-conformance	Ch	nief Eng	Descr	iption		Date	Verification	۱	QC Inspector
Design														
Doc/Data												•	Ì	
Equip/Tooling	_					1								
Handling/Pre													ı	
Material		1	1 1							į				
Operator													1	
Offset/Setup	_	ŀ												
Process	_]	1										1	
Supplier	_												-	
Training	_	}												
Transport														
Unapproved	_							<u> </u>						
						FA	ULT CAT	TEGORY	<u> </u>					
Landir	ng Gear			r	General	_	٦		ſ			r		
-	Bending			\vdash	Bend	厂	-	'rogram	ļ	\vdash	Outside Dim	<u> </u>		Pressure/Forced
	_	lot Conce	ntric	<u> </u>	BOM/Route	\vdash	Grain			\vdash	Over/Under	.	\dashv	Set-up
	Cracks			-	Broken/Damage/Defect	<u> </u>	Hardwa			\vdash	Part Incorred			Temperature/Cure
		ink/Ripple	:/Wave	\vdash	Burrs	<u> </u>	1 '	ion Incomplete/Ur	· ·	_	Part Lost/Mi	ssing		Weld
-	Cuffs			-	Contamination	-	-	ions Incomplete/U	Inclear	\vdash	Part Moved	L		Wrong Stock Pulled
	Crushing			-	Countersink	<u> </u>	-	ned/off center	ļ	-	Positioned W		\neg	- · ·
ļ	Heat Tre			<u> </u>	Cut Too Short	<u> </u>	Mislabe		ļ	<u>Ш</u>	Power Loss/S	Surge	19	Other
}		on Strip in	fube	\vdash	Drawing	\vdash	Misread	1		_		· 		
	Marks/C				Drill Holes	<u> </u>	Off-set			_	 			-a
		Sequence		\vdash	Finish	\vdash	4	Calibration		_				
ľ	[Wave/Tv	wist in Tub	e e	1	Fit/Function	1	1Out of 9	Sequence						

103515 .Work Order ID 103515 Page 2 June-24-13 1:57:24 PM Accept Start Item 1D: 646.3316 *N900040100* Setup Revision ID: Blade Item Name: *10* Start Qty: 10.00 6/24/13 Cust Item ID: Start Date: Required Date: 7/05/13 Reg'd Oty: 10.00 *10* Customer: Reference: Run Process Plan: _____ Date: ____ Tooling: Date: Approvals: Stop SPC (Y/N): Date: Date: Set Up/ Tool # Plan Accept Reject Reject Insp. Tool ID Sequence ID/ Operation Qty Number Stamp Code Qty Work Center ID Description . Run Hours OC2-Inspect parts off machine FAI/FAIB 0.00 120 \$13-07-28 *120* 0.00 Memo Quality Control 29 3.7.29 0.00 QC8- Inspect parts - second check 130 *130* 0.00 QC Memo Quality Control

140

Outsource process - Heat Treat

0.00

0.00

140

Outsource process - Heat Treat

Outsource1 Memo

HEAT TREAT AS PER DWG, SEE NOTE #3

ISSUE P/O: 20753

CX 13/08/09 10

. •

DQA:		Date:										DART
QA Closed:		Date:			WORK ORDER NON-	-CC	ONFOI	RMANCE / U		Work Order เ	pdate only	AEROSPACE
Mork Orde	NE'			_	DISPOSITION				AGAINST I	DEPARTMEN	T/PROCESS	
Work Orde	:I				Rework	1		Skid-tube	Crosstube	\neg	Water Jet	Engineering
Part N	lo.				Scrap			Machining Machining	Small Fab	 Pr	od. Eng. Coor.	Quality
			<u> </u>	_	Use-as-is			noforming	Finishing		ore/Packaging	Other
NCR N	1o.				Suspected Unapproved			Large Fab	Composite		Supplier	-
Root				Desc	ription of work order update	ı	initial	Act		Sign &		
Cause	Dat	e Step	Qty	ļ	or non-conformance	Ch	ief Eng	Descr	ription	Date	Verification	QC Inspector
Design				ļ							ŀ	
Doc/Data		1		ļ	'							
Equip/Tooling										l l		
Handling/Pre				1	,	1						
Material												
Operator												
Offset/Setup	Щ											
Process												
Supplier												
Training												
Transport												
Unapproved			<u>_</u>	<u> </u>		<u> </u>			<u> </u>			
						FA	ULT CA	TEGORY		•	<u>.</u>	
Landi	ng Gear			_	General		-		-		- -	_
	Bendi	ng		L	Bend		Folio/F	Program	1	Outside Dir	mensions	Pressure/Forced
	Centre	Not Conce	ntric		BOM/Route	L	Grain			Over/Unde	r tolerance	Set-up
	Crack	;			Broken/Damage/Defect		Hardwa	re		Part Incorr	ect	Temperature/Cure
•	Crimp	/Kink/Rjpplo	e/Wave		Burrs		Inspect	ion Incomplete/Ur	nqualified	Part Lost/N	Missing	Weld
	Cuffs				Contamination		Instruct	tions Incomplete/l	Jnclear	Part Move	; [Wrong Stock Pulled
	Crush	ing			Countersink		Misalig	ned/off center	[Positioned	Wrong _	
	Heat 1	reat			Cut Too Short		Mislabe	eled		Power Loss	/Surge	Other
	Inspe	tion Strip in	1 Tube		Drawing		Misread	Ł				· -
	Marks	/Chatter			Drill Holes		Off-set					,
	Turnir	ng Sequence	2		Finish		Out of (Calibration				
	Wave	/Twist in Tu	be		Fit/Function		Out of 9	Sequence				

Work Orden June-24-13 1:57:		3515		*10:	3515*					Page 3
Revision ID:	46.3316	·	· .	Accept	*N900	<u>04010</u>)O* ⁽	Setup Start Stop	*N.9 *N.9	51* 52*
	/24/13 /05/13	Start Qty: 10.00 Req'd Qty: 10.00	*10* *10*		Cust Item I Customer:	ID:				i
	Process Pla	in:	Date:	Tooling: SPC (Y/N):		ate:	- -	Run Start Stop	*NF *NF	₹1* ₹2*
Sequence ID/ Work Center ID 150 *150* Packaging Packaging		Operation Description Receive & Inspect for Dat Memo	mage & Mat'l Certs	Set Up/ Run Hours 0.00	Tool ID	Tool # Plar Cod			Reject Number	Insp. Stamp
155 *155* QC Quality Control		QC5- Inspect part comple Memo	eteness to step on W/O	0.00 OAS 0.00 16 89 .	13/08/13		<u>(410</u>)	, <u></u>	
*160 *160* SprayPaint Spray Painting		Spray Painting per QSI00 Memo PRIME AS I	95 4.2 PER DWG. SEE NOTE #4	0.00 0.00			_10_			A) 13-8-14

PRIMER BATCH: 126022

DQA:			Date:						- •	_			ື`∂∆RT
QA Closed:			Date:			WORK ORDER NON-	-C(ONFO	RMANCE / UP		Vork Order uj	ndate only	AEROSPACE
QA Closed.			Dotte.				_				 		
Work Orde	er:					DISPOSITION				AGAINST D	EPARTMENT	/PROCESS	
	-					Rework			Skid-tube	Crosstube		Water Jet	Engineering
Part N	۱o					Scrap		1	Machining	Small Fab	Pro	d. Eng. Coor.	Quality
						Use-as-is		Thern	noforming	Finishing	Rec/Sto	re/Packaging	Other
NCR N	Vo					Suspected Unapproved			Large Fab	Composite		Supplier	
Root	T				Desc	ription of work order update		nitial	Actio	on	Sign &		
Cause	į.	Date	Step	Qty		or non-conformance	ŀ	ief Eng	Descri		Date	Verification	QC Inspector
Design								, ,		<u>. </u>			
Doc/Data													
Equip/Tooling													
Handling/Pre													
Material													
Operator		•									1		
Offset/Setup			!										
Process]										
Supplier													
Training			•										
Transport													
Unapproved													
							FA	ULT CAT	TEGORY				
Landir	ng Ge	ar				General		-			_		<u></u>
	Ве	ending				Bend		Folio/P	rogram	L	Outside Dim	ensions	Pressure/Forced
	Ce	entre No	ot Concer	itric		BOM/Route	L	Grain			Over/Under	tolerance	Set-up
	c	acks			L	Broken/Damage/Defect	L	Hardwa	re		Part Incorred	ct _	Temperature/Cure
	Cr	imp/Kir	rk/Ripple,	/Wave		Burrs	<u></u>	Inspecti	ion Incomplete/Und	qualified	Part Lost/Mi	ssing	Weld
,	cı	ıffs				Contamination	匚	Instruct	ions Incomplete/Ui	nclear	Part Moved		Wrong Stock Pulled
	Щcг	ushing				Countersink		Misalig	ned/off center		Positioned V	Vrong	_
	Щн	eat Trea	it			Cut Too Short	L	Mislabe	eled		Power Loss/	Surge	Other
	ШIn	spection	n Strip in	Tube		Drawing		Misread	1		<u> </u>		
	М	arks/Ch	atter			Drill Holes	L	Off-set					
	Ŭ Tı	irning S	equence			Finish		Out of 0	Calibration				
	Ιlw	ave/Tw	ist in Tub	P		Fit/Function	1	Out of s	Contience		1		

H:/FORMS/Quality Assurance\approved QA/NCRWO RevH

Work Ord June-24-13 1:5		3515		*103	3515*	_						Page	4
Item ID: Revision ID: Item Name:	646.3316 Blade		*40*	Accept	*N900		100) *	Setup	Start Stop	*N:	S1*. S2*	:
Start Date: Required Date Reference:	6/24/13 : 7/05/13	Start Qty: 10.00 Req'd Qty: 10.00	*10* *10*		Cust Item I Customer:	ט:			_	.			
Approvals:	Process Pl	an:	Date:	Tooling:	Da	ate:		J	Run	Start	*N	R1*	
	QC:		Date:	SPC (Y/N):	Da	ate:				Stop	*N	R2*	
Sequence ID/ Work Center I 170 *170* QC Quality Control	ID	Operation Description QC14- Inspect Spray Pair Memo	ıt	Set Up/ Run Hours 0.00	Tool ID	Tool#	Plan Code	Accept Qty /O	Qty	' 1	Reject Number	Insp. Stamp	_13:08:1
180 *180* Packaging Packáging		Identify as per dwg & Sto Memo ***IDENTIF	Y AS PER APICAL MPF	0.00	# AND REV***			_/0!	<u> </u>			-8 13-8) 2-/
*190 *190* QC Quality Control		QC21- Final Inspection - Memo	Work Order Release	0.00				MU	∑	13-6	S 13	-08-	19

DQA:		_ Date:						_				TART
QA Closed:		Date:			WORK ORDER NON	-C(ONFO	RMANCE / UPDATE	14.	ork Order up	odata only	AEROSPACE
LA CIUSEU.		Date.							70	OIK OIGEI U	date only	
Work Orde	er:				DISPOSITION			AGAINS	T D	PARTMENT,	/PROCESS	
	-			-	Rework	1		Skid-tube Crosstub	e 🗆	1	Water Jet	Engineering
Part N	lo.				Scrap			Machining Small Fa	_	Pro	d. Eng. Coor.	Quality
					Use-as-is		Therr	noforming Finishir	ng[Rec/Sto	re/Packaging	Other
NCR N	lo			_	Suspected Unapproved			Large Fab Composit	ε]	Supplier	
Root	<u> </u>	T		Descri	ption of work order update		I Initial	Action		Sign &		
Cause	Date	Step	Qty	_ 000.	or non-conformance	1	nief Eng	1		Date	Verification	QC Inspector
Design		<u> </u>				Г						
Doc/Data												
Equip/Tooling												
Han d ling/Pre												
Material [1 1									
Operator						ĺ						·
Offset/Setup			1									
Process												
Supplier												
Training			1 1			-						
Transport												
Unapproved												
						FA	ULT CA	TEGORY				
Landir	ng Gear				General		_			_		_
	Bending				Bend	L	Folio/F	Program	L	Outside Dim	ensions	Pressure/Forced
	Centre N	ot Conce	ntric		BOM/Route		Grain		L	Over/Under	tolerance	Set-up
	Cracks				Broken/Damage/Defect		Hardwa	are		Part Incorred	ct	Temperature/Cure
	Crimp/Ki	nk/Ripple	e/Wave		Burrs		Inspect	ion Incomplete/Unqualified		Part Lost/Mi	ssing	Weld
	Cuffs				Contamination		Instruct	tions Incomplete/Unclear		Part Moved		Wrong Stock Pulled
[Crushing 				Countersink		Misalig	gned/off center		Positioned V	Vrong	_
	Heat Tre	at			Cut Too Short		Mislabe	eleď		Power Loss/	Surge	Other
	Inspection	n Strip in	Tube		Drawing		Misread	d				
[Marks/C	hatter			Drill Holes		Off-set					
[Turning S	Sequence			Finish		Out of	Calibration				
ſ	Wave/Tu	vist in Tub	he		Fit/Function	Г	Out of	Saguenca				

June-24-13 1:57:23 PM

Work Order ID:

103515

Parent Item:

646.3316

Parent Item Name:

Blade

Start Date: 6/24/13

Required Date: 7/05/13

Start Qty: 10.00

Required Qty: 10.00


Comments:


IPP REV:A NEW ISSUE 12/11/07 JFS VERIFY BY: JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
MSTEEL-A2- B0.500X1.250 AISI A2 TOOL STEEL BA	AR, 0.500 X 1.250	Purchased	No			100	f	2.7576	0.5 S	5.263158 7.167	SI	13-07	1-28

Location	Loc Oty	Loc Code	
MAT009	2.7576001		
123250	10000001		
125350	2.7576		
126166			<u>5.167'</u>

DQA:		_ Date:										"ANDT
۵۸ دامیمیا،		Data			WORK ORDER NON-	-C(ONFO	RMANCE / UPDATE	1.0	lauli Oudau	.d	AEROSPACE
QA Closed:		Date:					Γ—			ork Order up	odate only	<u> </u>
Work Orde	r:				DISPOSITION			AGAII	NST D	PARTMENT	/PROCESS	
				_	Rework]		Skid-tube Crosstu	ube	7	Water Jet	Engineering
Part N	0.				Scrap			Machining Small		Pro	d. Eng. Coor.	Quality
					Use-as-is	1		noforming Finish	ing	-	re/Packaging	Other
NCR N	o				Suspected Unapproved		:	Large Fab Compos			Supplier	
			,									
Root		1		Desc	ription of work order update	ı	Initial	Action		Sign &		
Cause	Date	Step	Qty		or non-conformance	Ch	nief Eng	Description		Date	Verification	QC Inspector
Design	_											
Doc/Data		Ì										
Equip/Tooling												
Handling/Pre										Ì		
Material		1				ŀ						
Operator	_											
Offset/Setup	_											
Process	_					ļ						
Supplier	_					ĺ						
Training	_											j [*]
Transport	_					ĺ						
Unapproved								TCODY				<u> </u>
						FAI	ULI CAI	regory				
Landin F					General]			7		٦, ،
	Bending Centre N	at Canaa		\vdash	Bend BOM/Route	<u> </u>	•	rogram	\vdash	Outside Dim	ļ	Pressure/Forced
-	Cracks	or concer	TUTIC	\vdash	Broken/Damage/Defect	\vdash	Grain		-	Over/Under	├	Set-up
-	Crimp/Kii	nk/Binnla	Maria	\vdash	Burrs	ļ	Hardwa		-	Part Incorred	<u> </u>	Temperature/Cure
}	Cuffs	rik/kippie	yvvave	\vdash			₹ `	on Incomplete/Unqualified	\vdash	Part Lost/Mi	ssing	Weld
-	Crushing			-	Contamination Countersink	_	₹	ions Incomplete/Unclear	-	Part Moved		Wrong Stock Pulled
}	Heat Trea			<u> </u>	Cut Too Short		Mislabe	ned/off center	\vdash	Positioned V Power Loss/:		Joshan
-	Inspectio		Tuba		Drawing	\vdash	Misread		L	Trower rossy:	ourge	Other
}	Marks/Cl	•	iuue	\vdash	Drill Holes	⊢	Off-set	ı				
-	Turning S			<u> </u>	Finish	\vdash	ł	Calibration				
+	Wave/Tw			-	Fit/Function	-	-1	Sequence				
					,		~~~~~					





•	·		


SHEEL ? P.

ZHEEL 3' ZECLION NIEW A-A, 15:

DEZCKILLION


YTO

FAN TC PART NUMBER




MATERIAL/SPECIFICATION


-		




		·





	•		
	·		
·			
•			
•			
•			




•			
•			
		,	









	•		
•			
•			
▼			







646.3315


APICAL INDUSTRIES


260 TEMPLE HEISHIS DR
OCEANODE CA 92050 3517 (260724-1300)

UPPER CUTTER ASSY

187 SCALE SON 1 167 SCALE SON 1 17 SCALE SO

			•	
		,		
			•	
	٠			
			•	
•				
	•			
•				
-				
•				
· . •	.			
	·		,	·





DART AEROSPACE LTD	Work Order:	103 515
Description: Black	Part Number:	646 3316
Inspection Dwg: 646 3300 Rev: NC		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

Drawing	Tolerance	Actual	Accept	Reject	Method of Inspection	Comments
Dimension	1	Dimension			5108	
5.87	+1-000	5.865			300	Ven
4.75	+/010	4.755	1			
. 94	+/010	.9415				
4,75 .94 .524	+1- ,005	o524	J			
R.125	4- 005	.125				
. 240	1/002	240	1			
.694 .524 45°	+1002	.695 .523 45°			Height	Gauge
.524	1/005	<i>•</i> 523	U			
45°	+/5°	45°	7			
1,250	+1002	1.250	J			
177	+.005/001	0178	/ .			
.375	4.005	,3755	·			
,375 Y 30°	+/005 X.5"	.325v30"			U	
				-		
			· · · · · · · · · · · · · · · · · · ·			
			<u> </u>			·
	 					
<u> </u>	 			<u> </u>		<u> </u>
	1	<u> </u>		L		<u> </u>

Measured by:	Audited by:	Preliminary Approval:
Date: 13-07-29	Date: 13 7 2 9	Date:
<u> </u>		

		•		
Rev	Date	Change	Revised by	Approved
E	10.04.14	Added preliminary approval	KJ	

* 1

METCOR INC.

560 BOUL. ARTHUR-SAUVÉ ST-EUSTACHE, QC J7R 5A8 Tel: 450-473-1884 / Fax: 450-491-5498

Recu de livraison.

Delivery Receipt

4,

BON DE TRAVAIL	EXPÉDITEUR	BON D'EXPÉDITION
Order	Shipper ID	Shipper
188318	1	73747

EXPÉDITION COMPLÈTE / Shipped Complete

CLIENT / Customer

215

DART AEROSPACE 1270 ABERDEEN

HAWKESBURY, ON K6A 1K7

Ph: 613-632-5200 Fax: 613-632-1053 LIVRÉ À /Shipped To

DART AEROSPACE

1270 ABERDEEN

HAWKESBURY, ON K6A 1K7

Ph: 613-632-5200 Fax: 613-632-1053

COMMANDE I Custome		BON DE LIVRAISON DU CLIENT Customer Shipper No.	TYPE DE MATÉRIEL Material Type	DATE DE LA COMMANDE Order Date	TRANSPORTEUR Carrier
PO207	753		A2	2013/8/1	fedex
QUANTITÉ Quantity	No. PIÈCI Part No.		DESCRIPTION DI Part Descripti	ı	POIDS Weight

10 646.3316

(10) BLADE

REFERENCE 103515

MAT: AISI A2 TO 58-62 RC

CONTENANT: 1 BOÎTE DE CARTON

TYPE DE CONTENEUR Container Type	# DE CONTENEURS # Of Containers	COMMENTAIRES CONTENEUR Container Comments	
BOITE DE CARTON	1		
EMPAQUETAGE Packing		QUANTITÉ EXPÉDIÉE / Quantity Shipped : POIDS EXPÉDIÉ / Weight Shipped :	10 4,00
	QU	ANTITÉ RESTANTE / Quantity Remaining :	0
		POIDS RESTANT / Weight Remaining :	0,00

QUANTITÉ EXPÉDIÉE /Quantity Shipped:	10
POIDS EXPÉDIÉ / Weight Shipped :	4,00

Signature:

Date:

EXPÉDIÉ LE / Shipped On: 2013/08/07

F-050-06 Rev. B

•		
	·	
• •		

560, boul. Arthur-Sauvé, St-Eustache (Québec) J7R 5A8 Tél. 450 473-1884 Télécopieur/Fax administration 450 491-5498 Télécopieur/Fax production 450 491-6454

Rapport d'Inspection

Inspection Report

BON DE TRAVAIL	CHARGEMENT	
order	load	
188318	1	

CLIENT / oustomer 215 DART AEROSPACE 1270 ABERDEEN

HAWKESBURY

ON K8A 1K7

LIVRÉ À / shipped to: DART AEROSPACE 1270 ABERDEEN HAWKESBURY

ON K8A 1K7

COMMANDE DU CLIENT customer po	BON DE LIVRAIBON DU CLIENT	MATÉRIEL	CODE DE TRAITEMENT	NUMÉRO DE LOT
	CUSTOMET Shipper no.	material	mat'l heat code	lot number
PO20753		A2		

SPÉCIFICATIONS DU PROCÉDÉ

processing specifications

VAC HARDEN

HARDEN AND TEMPER

:XIGENCE / requirement | SPÉCIFICATIONS / specifiedTESTS EXÉCUTÉS / performed | RÉSULTATS DE TESTS / results |
HARDNESS | 58 - 82 HRC | 5 | 58.0 - 80.0 HRC

QUANTITÉ quantity	POIDS weight	DESCRIPTION DES PIÈCES parts description	
10	4	646.3316 (10) BLADE REFERENCE 103515 MAT: AISI A2 TO 58-62 RC	
		CONTENANT: 1 BOÎTE DE CARTON	13 April

COMMENTAIRES / comments

CERTIFIÉ par / Certified by: DATE: 2013-08-07

			·	
			·	·
	• •			
 • •	**e e,	į		